

CSR PROJECT

Progress of Nathelav Project
beautification work of the
year 2020-2021

by

BANSWARA SYNTEX LIMITED



PROGRESS REPORT

- Pathway wall side (water body side) soil filling for plantation
- Water hyacinth removal from the talab back side area
- Water hyacinth removal from the talab crematorium side area
- Unwanted bushes plant cutting after 2nd ghat area

Pathway wall side (water body side) soil filling for plantation

Before

After



Water hyacinth removal from the talab back side area

Before



After



Water hyacinth removal from the talab crematorium side area

Before

After



Jalkumbhi removal from talab crematorium side area

Year – 2019-2020

Year- 2020 -2021



Water hyacinth removal from the talab crematorium side area

Before

After



Unwanted bushes plant cutting after 2nd ghat area

Before



After





Thank You